


5 MACRO

5.1 Introduction of Macro

Traditional NC programs have limited functions, such as being unable to operate and have no if functions.

Macro commands provide a higher level method of syntax utilization. Functions such as IF, GOTO, functions, variables, etc. are available and bring users more flexibility.

When adopted in systems, in order to let users to call and execute a series of often-used operations with a simple command, users can develop Macro programs to fulfill the need :



5.2 MACRO Call

Command Format	Description	Example
M98 P_ L_ M98 "string" L_ M98 "string"P_ L_	M98 call sub-program L : Repeat times P : 4digits sub-program number (O+ P_No) "string" : Appoint string arbitrarily "string"P_ : Combination file name(string+4 digits of P_NO)	<ul style="list-style-type: none"> ● M98 P1 L2; Description : Call O0001 twice. ● M98 "HELLO" L2; Description : Call HELLO twice. ● M98 "ABC" P1 L2; Description : Call ABC0001 twice.
G65 P_ L_ <arguments...> G65 "string" L_ <arguments...> G65 "string"P_ L_ <arguments...>	G65MACRO single call <arguments...> : send to MACRO arguments L : Repeat times P : 4digits sub-program number (O+ P_No) "string" : Appoint string arbitrarily "string"P_ : Combination file name(string+4 digits of P_NO)	<ul style="list-style-type: none"> ● G65 P1 L2 A11 B12 C13; Description : Call O0001 twice. Send to arguments cooreponding to #1=11、#2=12、#3=13。 ● G65 "HELLO" L2 A11 B12 C13; Description : Call HELLO twice. Send to arguments cooreponding to #1=11、#2=12、#3=13。 ● G65 "ABC" P1 L2 A11 B12 C13; Description : Call ABC0001 twice. Send to arguments cooreponding to #1=11、#2=12、#3=13。
G66 P_ L_ <arguments...> G66 "string" L_ <arguments...> G66 "string"P_ L_ <arguments...>	G66MACRO mode call <arguments...> : send to MACRO arguments L : Repeat times P : 4digits sub-program number (O+ P_No) "string" : Appoint string arbitrarily "string"P_ : Combination file name(string+4 digits of P_NO)	G66 P0001 L2 A11 B12 C13; X21.Y21. X22. Y22. Description : Call O0001 twice. Send to arguments cooreponding to #1=11、#2=12、#3=13;the following movement single block will call O0001 twice.
G_ <arguments...>	G code call MACRO <arguments...> : send to MACRO arguments	G22 A11 B12 C13; Description : If directory <maker_macro> has file maker_macro_g22, then system will call this file one time, and send to arguments to correspond to #1=11、#2=12、#3=13。
M_ <arguments...>	M code call MACRO	M23 A11 B12 C13;


	<arguments...> : send to MACRO arguments	Description : If directory < maker_macro > has file maker_macro_m23 , , then system will call this file one time, and send to arguments to correspond to #1=11 、 #2=12 、 #3=13 。
T_ <arguments...>	T code call MACRO <arguments...> : send to MACRO arguments	T24 A11 B12 C13; Description : If directory < maker_macro > has file maker_macro_t0, then system will call this file one time, and send to arguments to correspond to #1=11 、 #2=12 、 #3=13 。

Special Call Macro	Description
First time to do cyclestart to call MACRO	Version : Milling machine INT modemill_int_Ver03.01.53 If directory<macro>has file sys_func_init1, then system will run this MACRO one time when doing first time cyclestart. If directory <macro_maker> has file maker_func_init1, then system will run this MACRO one time when doing first time cyclestart. If above two files exist at the same, then system will run sys_func_init1 and then maker_func_init1 in order.
Every time to do cyclestart to call MACRO	Version : Milling machine INT modemill_int_Ver03.01.53 If directory <macro> has file sys_func_startup1, then system will run this MACRO one time when doing every time cyclestart. If directory <macro_maker> has file maker_func_startup1, then system will run this MACRO one time when doing every time cyclestart. If above two files exist at the same, then system will run sys_func_startup1 and then maker_func_init1.

5.3 MACRO return method


M99 : Finishing sub-program to go back to main program

- (1.) When executing M99 in the main program, system will go back to the top of program to run again.
In the sub-program, you will need to use M99 to do the ending and make it go back to main program.
- (2.) Command format : M99 P__ ;
P__ : appointed return line number
If main program has M99 P_, then system will find the line number that M99 appointed and run ;
When using M99 P_at the ending of sub-program, M99 will run from the appointed line number, after sub-program finishes and returns to main program, as below :



5.4 Send MACRO arguments method

Call MACRO can be via NC address (english letters, expect G、N) to send in arguments, there is no order of them. These arguments has corresponding local variables from MACRO, as below :



Variables corresponding list as below :

A~Z										
NC address	A	B	C	D	E	F	G	H	I	J
Local variables	#1	#2	#3	#4	#5	#6	X	#8	#9	#10
NC address	K	L	M	N	O	P	Q	R	S	T
Local variables	#11	#12	#13	X	#15	#16	#17	#18	#19	#20
NC address	U	V	W	X	Y	Z				
Local variables	#21	#22	#23	#24	#25	#26				

5.5 MACRO saving directory and file type description

There are 3 types of system program and MACRO saving directory. System directory is <macro>, machine maker's directory is <maker_macro>, and end-users' directory is <ncfile_1>, as below. Milling machine MACRO file list is at the appendix A.

Directory	File Type	File Type Example	Description
macro	sys_macro_g##	sys_macro_g35	G code call system MACRO
	sys_macro_m##	sys_macro_m35	M code call system MACRO
	sys_macro_t0	sys_macro_t0	All T code call this system MACRO
	sys_modal_g##	sys_modal_g81	System MACRO mode call is INT basic command
	sys_single_g##	sys_single_g53	System MACRO single time call is INT basic command
	sys_func_mdi1		Inset MACRO manually
	sys_func_prog_restart1		Program restart to call this system MACRO
	sys_func_start_init1		When file exists,system will run this MACRO one time at the first time cycle start.
	sys_func_startup1		When file exists,system will run this MACRO one time in advance
maker_macro	maker_macro_g##	maker_macro_g35	G code call machine maker MACRO
	maker_macro_m##	maker_macro_m35	M code call machine maker MACRO
	maker_macro_t0	maker_macro_t0	All T code call this machine maker MACRO
	maker_func_start_init1		When file exists,system will run this MACRO one time at the first time cycle start.
	maker_func_startup1		When file exists,system will run this MACRO one time in advance
ncfile_1	o####(4 digits)	o1234	This file format offer M98 call sub-program , or for G65、G66 to call MACRO
	###...(32 digits)	test1234	Normal file name, support 32 english letters

5.6 System MACRO, machine maker MACRO and end-user MACRO usage rule

MACRO arguments usage rule

- a. If there is GMT call MACRO in single block program, then all words in this line will turn to argument, except below :
 - G、N code
 - GMT call MACRO code
- b. If there are 2 and above GMT call MACRO in single block program, then the first showing one will be call MACRO code, the coming one will be treated as arguments.

- When P#50072 MACRO mode call type(0:default,1:single level) setting is 1, system MACRO , machine maker MACRO and end-user MACRO has rules as below :
 - a.If "MACRO mode call "meets"MACRO single time call" , "MACRO single time call" will be run first.
 - b." End-user MACRO mode call " meets" system MACRO mode call " , " system MACRO mode call " will be run first.
 - c.The same type MACRO mode call in the same level, the following MACRO mode call setting will cover previous setting.
 - d.MACRO mode call allows "the same level, but different type next call" or "the same type but different level next call", but do not accept overlap call.
 - e.GMT code call MACRO, machine maker MACRO will be run firstly, and then run system MACRO.
EX : there is maker_macro_g33 and sys_macro_g33, system will run maker_macro_g33.
 - f.MACRO mode call only valid in this level.

c. MACRO mode call features :

system MACRO mode call	Call timing	Every single block with axis command
	Cancel timing	1. G80 command cancel this setting level 2. G code group [1] movement command cancel this setting level 3. M99 command cancel this setting level 4. M30 command cancel this setting level
end-user MACRO mode call	Call timing	G code group[1] movement command call
	Cancel timing	1. G67 command cancel this setting level 2. M99 command cancel this setting level 3. M30 command cancel this setting level

d. Sub-program and MACRO level limitation :

System	“System MACRO mode call” and “system MACRO single call” -maximum combination can be 8 levels.
	“System sub-program”, “system MACRO mode call ” and “system MACRO single call” -maximum combination can be 12 levels.
User	“End-user MACRO mode call” and “user MACRO single call” -maximum combination can be 4 levels.
	“End-user MACRO mode call”, “end-user MACRO mode call ” and “user MACRO single call” -maximum combination can be 6 levels.

e. In the MACRO call program, if there is a GMT code call file with the same name, then it will be treated as a normal GMT code.

6 Operand Priority

This chapter is to explain whole series of INT mode.

Version : Milling machine INT mode **mill_int_Ver03.01.01**

6.1 Operand Priority

Description as below :

Operand	Symbol	Priority
Parentheses	()	1
Function	xxxx();	2
Minus	-	3
NOT operation	!	
Multiplication	*	4
Division	/	
Addition	+	5
Subtraction	-	
Comparison	>, <, >=, <=, ==, !=	6
AND logic operation	&&	7
OR logic operation		8
XOR logic operation	^	9

6.2 Mathematic Operation Command

(1). Substitution, =

#i = #j

(2). ADDITION , +

#i = #j + #k

(3). SUBTRATION , -

#i = #j - #k

(4). MULTIPLICATION , *

#i = #j * #k

(5). QUOTIENT , /

#i = #j / #k

(6). PARENTHESIS , ()

#i = #j * (#k + #l)

6.3 Logic Operation Command

(1). AND logic operation, &&

#i = #j && #k

0 for false and non-0 for true in logic operation

(2). OR logic operation, | |

#i = #j | | #k

(3). NOT logic operation, !

#i = ! #j

6.4 Compare Command

(1) Greater Than (GT), >

#i = #j > #k , If #j is greater than #k, then the statement is true, #i=1.

(2) Less Than (LT), <

#i = #j < #k , If #j is less than #k then the statement is true, #i=1.

(3) Greater Than or Equal to (GE), >=

#i = #j >= #k , If #j is greater than or equal to #k, then the statement is true, #i=1.

(4) Less Than or Equal to (LE), <=

#i = #j <= #k , If #j is less than #k, then the statement is true, #i=1.

(5) Equal , ==

#i = #j == #k , If #j is equal to #k, then the statement is true, #i=1.

(6) Not Equal , !=

#i = #j != #k , If #j is not equal to #k, then the statement is true, #i=1.

7 Expression

This chapter is to explain whole series of INT mode.

Version : Milling machine INT mode **mill_int_Ver03.01.01**

7.1 IF~GOTO

A. Conditioned Jump

Method : IF (<Conditional express>) GOTO n

Description : IF <Conditional express> condition is true, then jump to the block numbered “n”, else continue the next block

Example :

IF(#1>3) GOTO 1001;

G01 X10.;

...

N1001 G01 X20.;

...

M30;

B. Unconditioned Jump

Method : GOTO n

Description : Jump to the block numbered “n” directly.

Example :

GOTO 1001;

G01 X10.;

...

N1001 G01 X20.;

...

M30;

7.2 IF...ELSE

Method :

IF(conditions described)

 Data Process;

ELSEIF(conditions described)

 Data Process;

ELSE

 Data Process;

END_IF

Description : IF...ELSE select described

Example :

#1=2

G0 X0.

IF(#1==1)

 G0 X10.

ELSEIF(#1==2)

 G0 X20.

ELSE

 G0 X30.

END_IF

G0 X40.

M30

7.3 SELECT

Method :

SELECT(Integer or calculating formula)

CASE Integer :

 Data Process;

CASE Integer, Integer, Integer, Integer :

 Data Process;

CASE_ELSE

 Data Process;

END_SELECT

Description : SELECT (select described)

Example :

#1=2

G0 X0.

SELECT(#1)

CASE 1:

 G0 X10;

CASE 2:

 G0 X20;

CASE 3,4,5,6:

 G0 X30.

CASE_ELSE

 G0 X99.

END_SELECT

M30

7.4 FOR

A. Not use INC variables

Method :

FOR variables=loop's initial value or calculating formula TO loop ending value or calculating formula

Data Process;

END_FOR

Description : FOR loop.

Example :

G0 X0.

FOR #1=11 TO 23

G0 X#1;

END_FOR

M0; /* X axis final movement position 23mm , #1 final is 24 */

M30

B. Use INC variables

Method :

FOR variables= loop's initial value or calculating formula TO loop ending value or calculating formula

STEP loop accumulated value or calculating formula

Data Process;

END_FOR

Description : FOR loop.

Example :

G0 X0.

FOR #1=11 TO 23 STEP 2

G0 X#1;

END_FOR

M0; /* X axis final movement position 23mm , #1 final is 25 */

M30

7.5 EXIT_FOR

Method :

FOR variables=loop's initial value or calculating formula TO loop's endingl value or calculating formula STEP loop acccumulated value or calculating formula

 EXIT_FOR

 END_FOR

Description : leave FOR loop

Example :

 G0 X0.

 FOR #1=11 TO 23

 G0 X#1;

 IF(#1>15)

 EXIT_FOR; /* when #1=16, leave loop */

 END_IF

 END_FOR

 M0; /* X axis final movement position 16mm , #1final is 16 */

 M30

7.6 WHILE

Method :

WHILE(conditions described)

 Data Process;

 END_WHILE

Description : WHILE loop

Example :

 G0 X0.

 #1=2

 WHILE(#1<10)

 G0 X#1

 #1=#1+1

 END_WHILE

 M0; /* X AXIS FINAL MOVEMENT POSITION9mm , #1final is 10 */

 M30

7.7 EXIT_WHILE

Method :

WHILE(conditions described)

 EXIT_WHILE

 END_WHILE

Description : leave WHILE loop

Example :

G0 X0.

#1=2

WHILE(#1<10)

 G0 X#1

 IF(#1>8)

 EXIT_WHILE; /* When #1=9, leave loop */

 END_IF

 #1=#1+1

END_WHILE

M0; /* X AXIS FINAL MOVEMENT POSITION 9mm , #1final is 9 */

M30

7.8 DO...UNTIL

Method :

DO

 Data Process;

 UNTIL(conditions described)

Description : When the conditions are not established, repeat UNTIL loop

Example :

G0 X0.

#1=2

DO

 G0 X#1

 #1=#1+1

UNTIL(#1>=10)

M0; /* X AXIS FINAL MOVEMENT POSITION9mm , #1final is 10 */

M30

7.9 EXIT_DO

Method :

```
DO
    EXIT_DO
    UNTIL(conditions described)
```

Description : leave DO...UNTIL loop

Example :

```
G0 X0.
#1=2
DO
    G0 X#1
    IF(#1>7)
        EXIT_DO;      /* when #1=8, leave loop */
    END_IF
    #1=#1+1
    UNTIL(#1>=10)
    M0;           /* X AXIS FINAL MOVEMENT POSITION8mm , #1final is 8 */
M30
```

7.10 CALL_SUB

Method :

```
CALL_SUB "function name"
```

```
SUB "function name"
```

```
    Data Process;
```

```
END_SUB
```

Description : allow program to call the same file's function

Example :

```
G0 X0.
```

```
#1=3;
```

```
CALL_SUB "ABC_123"
```

```
G0 X99.
```

```
M30
```

```
SUB "ABC_123"
```

```
    G0 Y10.
```

```
    IF(#1>2)
```

```
        EXIT_SUB
```

```
    END_IF
```

```
    G0 Y20.
```

```
END_SUB
```

7.11 EXIT_SUB

Method :

```
EXIT_SUB
```

Description : leave function command

Example :

Refer to CALL_SUB call function description

8 Function

This chapter is to explain whole series of INT mode.

Version : Milling machine INT mode **mill_int_Ver03.01.01**

8.1 Function List

Mathematical function	Description	R/W
SIN(DEG)	SIN Number of function	R
COS(DEG)	COS Number of function	R
TAN(DEG)	TAN Number of function	R
ASIN(VALUE)	ASIN Number of function	R
ACOS(VALUE)	ACOS Number of function	R
ATAN(VALUE1,VALUE2)	ATAN Number of function	R
SQRT(VALUE)	Get SQRT value	R
ABS(VALUE)	Get ABS value	R
ROUND(VALUE)	Get ROUND value	R
FIX(VALUE)	Get FIX value	R
MOD(VALUE1,VALUE2)	Get MOD value	R
Normal function		
WAIT(PATH,TYPE)	Stop interpretation	W
ALARM("STRING")	Command MACRO to send alarm	W
ALARM(PATH,ALARM_No)	Command system MACRO to send Alarm	W
TAN_FOLLOW(PATH,TYPE,VALUE)	Tan follow function setting	W
Read/write system info function		
R_G_GROUP(PATH, GROUP)	Read G code group	R
R_SYS_INFO(PATH, TYPE)	Read system info	R
TIME(TYPE)	Read system time	R
R_ARG(AXIS)	Get MACRO to 1~6 axis argument value	R
R_AXID("NAME")	Get path axis order	R
W_HSHP(PATH,TYPE,VALUE)	HSHP setting	W
R_SKIP(PATH,TYPE)	Read G31 Skip coordinate info	R
W_SKIP(PATH,TYPE,VALUE)	Write G31 Skip coordinate info	W
R_RESTART(PATH,TYPE)	Read program restart info	R
R_BREAKPOINT(PATH,TYPE)	Read manual return info	R
Read/write R and variables function		

Function

R_REG(R_No)	Read R value	R
R_REG_F(R_No)	Pre-read R value	R
R_REG_BIT(R_No,BIT)	Read R BIT value	R
R_REG_BIT_F(R_No,BIT)	Pre-read R BIT value	R
W_REG(R_No,VALUE)	Write R value	W
W_REG_SYNC(R_No,VALUE)	Write R value with SBK synchronizely	W
W_REG_BIT(R_No,BIT,ONOFF)	Write R BIT value	W
W_REG_BIT_SYNC(R_No,BIT,ONOFF)	Write R BIT by SBK SYN	W
R_LV_BIT(LV_No,BIT)	Read Local variables BIT	R
W_LV_BIT(LV_No,BIT,ONOFF)	Write Local variables BIT	W
R_GV_BIT(GV_No,BIT)	Read global variables BIT	R
W_GV_BIT(GV_No,BIT,ONOFF)	Write Global variables BIT	W
Read/write coordinate and coordinate function		
R_ABS_COOR(PATH,AXIS)	Read MOT ABS coordinate	R
R_MACH_COOR(PATH,AXIS)	Read MOT MACHINE coordinate	R
W_ABS_SHIFT(PATH,AXIS,CASE,VALUE)	Command MOT coordinate Offset	W
R_INT_PROG_COOR(PATH,AXIS)	Read INT Program Coordinate	R
INT_UPDATE(PATH,AXIS)	Make INT coordinate & MOT coordinate SYN	R
R_G53G59_COOR(PATH,Coor,AXIS)	Read G53~G59 coordinate	R
W_G53G59_COOR(PATH,Coor,AXIS,VALUE)	Write G53~G59 coordinate	W
R_G54EXP_COOR(PATH,Coor,AXIS)	Read G54 extension coordinate	R
W_G54EXP_COOR(PATH,Coor,AXIS,VALUE)	Write G54 extension coordinate	W
Read/write tool info function		
R_TOOL_DATA(PATH,Tool_No,TYPE)	Read INT tool info	R
W_TOOL_DATA(PATH,Tool_No,TYPE,VALUE)	Write INT tool info	W
I LATCH value function		
W_I_LATCH(PATH,I_NO,HwifAxis_No,Ri_Fa)	Set up I Latch	W
R_I_LATCH(PATH,I_NO)	Get if I Latch happen	R
R_I_LATCH_COOR(PATH,I_NO,AXIS)	Get I Latch coordinate	R
Regularization		
SPEED_STD(PATH,VALUE)	Speed value regularization	R
SPEED_STD_R(PATH,R_No)	R speed regularization	R
SPEED_STD_R_F(PATH,R_No)	Pre-read R Speed regularization	R
LEN_STD(PATH,AXIS,VALUE)	Length value regularization	R
LEN_STD_R(PATH,AXIS,R_No)	R Length value regularization	R
LEN_STD_R_F(PATH,AXIS,R_No)	Pre-read R length value regularization	R

In position function		
C_INPOS(PATH,TYPE,VALUE)	Feedrate in position check	W
RP_INPOS(PATH,TYPE,VALUE)	Rapid in position check	W
BKCMP(PATH,TYPE,VALUE)	SBK compare	W
MACRO variables stack function		
PUSH(VALUE)	Push to MACRO variable stack	W
POP()	Pop info from MACRO variables stack	R
STKTOP(STACK_NO)	Check info from MACRO variables stack	R
STKCLR()	Clear stack info	W
CCD function		
W_CCD(PATH,TYPE,VALUE)	Set up CCD info	W
PASER_CCD(PATH,ITEM)	Get CCD reply data column value	R
MACRO dialogue function		
MSG_OK("TITLE","TEXT","FILE")	Message dialogue	W
MSG_YES("TITLE","TEXT","FILE")	Inquiry dialogue	R
INPUT("TITLE","TEXT","FILE",MIN,MAX,DEF)	Input value dialogue	R
MENU("TITLE","TEXT","FILE")	Menu dialogue	R
MENU_ADD("TEXT","FILE")	Menu dialogue setting	W
PLOT_ADD("FILE","LEGEND")	Curve data file name	W
PLOT_SHOW("TITLE","TEXT","XLB","YLB")	Curve framce	W
MACRO write function		
OPEN("FILE")	Open file	W
CLOSE()	Close file	W
PRINT("STRING")	Write string	W

8.2 Mathematical function

SIN(DEG)		SIN	Number of function	R
Description	● DEG => Angle degree ◦ Value range****, unit : degree			
Reply	Value, value range****, unit : N/A			
Example	#1 = SIN(30); /* #1 Value=0.5 */			

COS(DEG)		COS	Number of function	R
Description	● DEG => Angle degree ◦ Value range****, unit : degree			
Reply	Value, value range****, unit : N/A			
Example	#1 = SIN(30); /* #1 Value=0.866 */			

TAN(DEG)		TAN	Number of function	R
Description	● DEG =>Angle degree ◦ Value range****, unit : degree			
Reply	Value, value range****, unit : N/A			
Example	#1 = TAN(30); /* #1 Value=0.57735 */			

ASIN(VALUE)		ASIN	Number of function	R
Description	● VALUE=> Value ◦ Value range-1~1, unit : N/A			
Reply	Angle degree ◦ Value range-90~90, unit : degree			
Example	#1 = ASIN(0.5); /* #1 Value=30 */			

ACOS(VALUE)		ACOS	Number of function	R
Description	● VALUE=> Value ◦ Value range-1~1, unit : N/A			
Reply	Angle degree ◦ Value range-90~90, unit : degree ◦			
Example	#1 = ASIN(0.866); /* #1 Value=30 */			

ATAN(VALUE1,VALUE2)		ATAN	Number of function	R
Description	● VALUE1=> On the other side of right triangle ◦ Value range****, unit : N/A ● VALUE2=> On the next side of right triangle ◦ Value range****, unit : N/A			
Reply	Angle degree ◦ Value range-180~180, unit : degree ◦			
Example	#1 = ATAN(0.57735,1); /* #1 Value =30 */			

SQRT(VALUE)		Get SQRT value	R
Description	● VALUE=> Value, value range****, unit : N/A		
Reply	Value, value range****, unit : N/A		
Example	#1 = SQRT(2); /* #1 Value=1.4142 */		

ABS(VALUE)		Get ABS value	R
Description	● VALUE=> Value, value range****, unit : N/A		
Reply	Value, value range****, unit : N/A		
Example	#1 = ABS(-2); /* #1 Value=2 */		

ROUND(VALUE)		Get Round value	R
Description	● VALUE=>Value, value range****, unit : N/A		
Reply	Value, value range****, unit : N/A		
Example	#1 = ROUND(1.7); /* #1 Value=2 */		

FIX(VALUE)		Get FIX value	R
Description	● VALUE=>Value, value range****, unit : N/A		
Reply	Value, value range****, unit : N/A		
Example	#1 = FIX(1.2); /* #1 Value=1 */		

MOD(VALUE1,VALUE2)		Get MOD value	R
Description	● VALUE1=>Value, value range****, unit : N/A ● VALUE2=>Value, value range****, unit : N/A		
Reply	Value, value range****, unit : N/A		
Example	#1 = MOD(24.95,5.5); /* #1 Value=2.95 */		

8.3 Normal function

	WAIT(PATH,TYPE)	Stop interpretation	W																		
	<ul style="list-style-type: none"> ● PATH =>path, No. ° Value range0 ~6, unit : N/A 0 : current belonging path, 1~6 : first path~6th path. ● TYPE =>Appointed type ° Value range****, unit : N/A 0: type I , Interpred single block has been executed. 1: type II , Interpred single block has been executed.+arrived machine coordinate. 																				
	Below function has been done stop interpretation(Type I)																				
Description	<table border="1"> <tr><td>R_REG</td><td>R_REG_BIT</td><td>W_REG</td></tr> <tr><td>W_REG_BIT</td><td>LEN_STD_R</td><td>SPEED_STD_R</td></tr> <tr><td>R_ABS_COOR</td><td>W_ABS_SHIFT</td><td>TIME</td></tr> <tr><td>W_I_LATCH</td><td>R_I_LATCH</td><td>R_I_LATCH_COOR</td></tr> <tr><td>W_CCD</td><td>WAIT_CCD</td><td>MSG_OK</td></tr> <tr><td>MSG_YES</td><td>INPUT</td><td>MENU</td></tr> </table>			R_REG	R_REG_BIT	W_REG	W_REG_BIT	LEN_STD_R	SPEED_STD_R	R_ABS_COOR	W_ABS_SHIFT	TIME	W_I_LATCH	R_I_LATCH	R_I_LATCH_COOR	W_CCD	WAIT_CCD	MSG_OK	MSG_YES	INPUT	MENU
R_REG	R_REG_BIT	W_REG																			
W_REG_BIT	LEN_STD_R	SPEED_STD_R																			
R_ABS_COOR	W_ABS_SHIFT	TIME																			
W_I_LATCH	R_I_LATCH	R_I_LATCH_COOR																			
W_CCD	WAIT_CCD	MSG_OK																			
MSG_YES	INPUT	MENU																			
	Below function has been done stop interpretation (Type II)																				
	<table border="1"> <tr><td>R_MACH_COOR</td><td>INT_UPDATE</td><td>R_RESTART</td></tr> </table>			R_MACH_COOR	INT_UPDATE	R_RESTART															
R_MACH_COOR	INT_UPDATE	R_RESTART																			
Reply	: N/A																				
Example	... WAIT(0,0); /* wait previous single block to be executed and read the coming single block */ ...																				

	ALARM("STRING")	Command MACRO to send Alarm	W
Description	<ul style="list-style-type: none"> ● STRING =>At least 1 digit's any string. If above arguments string has MACRO variables, system will replace it to be the value automatically. Refer to 5.5 string variables replace value chapter. 		
Reply	: N/A		
Example	<p>Usage Example 1 :</p> <pre>ALARM("did not open coolant"); /* send alarm 610000 and show string " did not open coolant" */</pre> <p>Usage Example 2 :</p> <pre>#1= R_MACH_COOR(0,1); /* If this path's machine coordinate first axis =1.234mm, #1Value=1.234 */</pre> <pre>ALARM("machine coordinateX#1correct"); /* send alarm 610000 and show string " machine coordinateX1.234 correct" */</pre>		

	ALARM(PATH,ALARM_No)	Command system MACRO to send Alarm	W
Description	<p>This function is only for system MACRO to use</p> <ul style="list-style-type: none"> ● PATH =>path number 。Value range 0 ~6, unit : N/A 0 : Current path , 1~6 : First path~6th path. ● ALARM_No =>Appoint alarm number(1~511) 。Value range1 ~ 511, unit : N/A 		
Reply	: N/A		
Example	ALARM(0,1); /* send alarm 610001 */		

	TAN_FOLLOW(PATH,TYPE,VALUE)	Tan-follow Function Setting	W
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range0 ~6, unit : N/A 0 : Current path, 1~6 : First path~6th path. ● TYPE =>Setting item, value range****, unit : N/A 1: Tan-follow function setting axis(0:N/A,1~3:Cartesian coordinate previous 3 axis), unit : N/A 2: Tan-follow direction(0:+,1:-), unit : N/A ● VALUE =>Write info, value range0 ~ 2147483647, unit : N/A 		
Reply	<p>Alarm :</p> <p>-1 => Direction is over range</p>		
Example	TAN_FOLLOW(0,1,3); /* Tan-follow function setting=3 rd axis */		

8.4 Read/write system info function

	R_G_GROUP(PATH,GROUP)	Read G code group	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● GROUP =>G group[0~22], value range0~22, unit : N/A 		
Reply	<p>Part program read G code group, unit : N/A</p> <p>Alarm :</p> <p>-1 => Group No. is ove range</p>		
Example	#1= R_G_GROUP(0,1); /* If current group 1=G2, #1Value=2 */		

	R_SYS_INFO(PATH,TYPE)	Read system info	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● TYPE =>Type, value range****, unit : N/A. 		

	0 : Path No., unit : N/A. 1: Get system type, 0:Main INT 1:Preview INT 2:R-restart, unit : N/A 2: Get Mode T code, unit : N/A 4: Get system speed, unit=mm/min 5: Get extention coordinate number, unit : N/A 6: Path axis numbers, unit : N/A 7: MACRO to 2 M arguments, unit : N/A 8: MACRO to 3 M arguments, unit : N/A 9: MACRO to 2 S arguments, unit : N/A 10: MACRO to 3 S arguments, unit : N/A 11: If path 1 is ON(0:N,1:Y) 12: If path 2 is ON(0:N,1:Y) 13: If path 3 is ON(0:N,1:Y) 14: If path 4 is ON(0:N,1:Y) 15: If path 5 is ON(0:N,1:Y) 16: If path 6 is ON(0:N,1:Y) 20: If HMI is invalid(0:Valid,1:Invalid), corresponding command DIS_HMIPLOT_ON 21: If mute is ON(0: N/A,1:mute), corresponding command MUTE_ON 22: If offset is invalid(0:Valid,1:Invalid), corresponding command DIS_SHIFT_ON 23:If external SBK stop is invalid(0:Valid,1:Invalid), corresponding command SBK_OFF 24: If fixed G0 override(0:N/A,1:Fixed 100%), corresponding command FIX_RAPID_OR_ON 。 25: If fixed G1 override(0: N/A,1:Fixed 100%), corresponding command FIX_CUT_OR_ON 。 26: If fixed auto mode(0: N/A,1:Fixed), corresponding command FIX_AUTOMODE_ON 。 101 ~ 132: Get 1~32 axis corresponding software axis number, unit : N/A
Reply	Part program read system info, unit=as above
Example	#1= R_SYS_INFO(0,2); /* If current situation T code=201, #1Value=201 */

	TIME(TYPE)	Read System Time	R
Description	This function will stop interpretation automatically.(Type I) <ul style="list-style-type: none"> ● TYPE =>Type, value range****, unit : N/A. <ul style="list-style-type: none"> 1: Get system interrupt times, unit : N/A 2: System date year : yyyy, unit : N/A 3 System date month : mm, unit : N/A 4: System date day : dd, unit : N/A 5: System time hour : hh, unit : N/A 6: System time 分 : nn, unit : N/A 		

	7: System time minute : ss, unit : N/A
Reply	Part program read system time, unit=as above
Example	#1= TIME(5); /* If current time=15:30, #1Value=15 */

R_ARG(AXIS)		Get MACRO to 1~6 axis argument value	R
Description	● AXIS=>Appoint axis number, value range1~32, unit : N/A		
Reply	MACRO to this axis argument value, unit=mm VACANT => This axis did not have arguments to pass in.		
Example	G65 P1234 X11. Y12. Z13. /* call O1234 MACRO */ ;/* O1234 */ #1= R_ARG(1); /* #1Value=11 */		

R_AXID("NAME")		Get path axis order	R
Description	● NAME=>Appoint axis, value range****, unit : N/A		
Reply	Reply path axis order No., unit : N/A VACANT => No this axis in the parameter setting Alarm : -1 => Did not appoint axis string -2 => Axis string format error		
Example	#1= R_AXID("X"); /* If path 1 axis=X, then #1Value=1 */ #2= R_AXID("Y2"); /* If path 2 axis =Y2, then #2Value=2 */ #3= R_AXID("Z3"); /* If path 3 axis =Z3, the #3Value=3 */		

W_HSHP(PATH,TYPE,VALUE)		HSHP setting	W
Description	● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● TYPE =>Setting item, value range****, unit : N/A 1: Path feedrate linear ACC/DEC time, unitms 。 7: Path feedrate 5mm arm allow speed, unitKLU/min 。 9: Feedrate circular clamp minimum speed, unitKLU/min 。 101 ~ 132: path feedrate 1~32 axis corner speed difference, unitKLU/min 。 ● VALUE =>Write info, value range0 ~ 2147483647, unit : N/A		
Reply	Alarm : -1 => Appoint value is illegal		
Example	W_HSHP(0,1,50); /* Set up path feedrate linear ACC/DEC time=50ms */		

R_SKIP(PATH,TYPE)		Read G31 Skip coordinate info	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● TYPE =>Type, value range****, unit : N/A. 1: If SKIP signal has been triggered(0:N,1:Y), unit : N/A 101 ~ 132: SKIP ABS coordinate 1~32 axis, unit=mm 201 ~ 232: SKIPMACHINE coordinate1~32 axis, unit=mm 		
Reply	Part program Read G31 Skip coordinate info, unit=as above		
Example	G91 G31 Z-100. F100; #1= R_SKIP(0,103); /* Get 3 axis SKIP ABS coordinate */ G04 X20.; /* feedhold, you can check if #1=Z axis ABS coordinate */ M30;		

W_SKIP(PATH,TYPE,VALUE)		Write G31 Skip coordinate info	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● TYPE =>Type, value range****, unit : N/A. 1: If SKIP signal has been triggered (0:N,1:Y), unit : N/A 101 ~ 132: SKIPABScoordinate1~32 axis, unit=mm 201 ~ 232: SKIPMACHINE coordinate1~32 axis, unit=mm ● VALUE =>Write info, value rangedouble, unit=mm 		
Reply	: N/A		
Example	W_SKIP(0,101,0); /* White SKIP 1 st axis ABS coordinate, write value=0 */		

R_RESTART(PATH,TYPE)		Read program restart info	R
Description	<p>This function will stop interpretation automatically.(Type II)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● TYPE =>Type, value range****, unit : N/A. 1~15:Secircularhed M code 21: Secircularhed S code 31~32: Secircularhed T code 101 ~ 132: Target site ABS coordinate 1~32 axis, unit=mm 201 ~ 232: Target site MACHINE coordinate 1~32 axis, unit=mm 301 ~ 332: Offset from current position to target site 1~32 axis, unit=mm 		
Reply	Part program read program restart info, unit=as above Alarm : -1 => Read coordinate error		

Example	#1=R_RESTART(0,101); /* read R-restart first axis target site ABS coordinate */
---------	---

R_BREAKPOINT(PATH,TYPE)		Read manual return info	R
Description	<p>This function will stop interpretation automatically.(Type II)</p> <ul style="list-style-type: none"> ● PATH => Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● TYPE => Type, value range****, unit : N/A. 101 ~ 132: Target site ABS coordinate 1~32 axis, unit=mm 201 ~ 232: Target site MACHINE coordinate 1~32 axis, unit=mm 301 ~ 332: Offset from current position to target site 1~32 axis, unit=mm 		
Reply	Part program Read manual return info, unit=as above Alarm : -1 => Read coordinate error		
Example	#1=R_BREAKPOINT(0,101); /* read manual return first axis target site ABS coordinate */		

8.5 Read/write R and variables function

R_REG(R_No)		Read R value	R
Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● R_No=> R location NO., value range0 ~ 179999, 1000000 ~ 5999999, unit : N/A 		
Reply	R VALUE, value range-2147483648 ~ 2147483647, unit : N/A Alarm : -1 => R value NO. is over range.		
Example	#1=R_REG(1); /* If R[1]=12, #1Value=12 */		

R_REG_F(R_No)		Pre-read R value	R
Description	This function will pre-read R bit, easy to have pre-INT problem, so need to use WAIT(...) to use, suitable for advanced programmer to use.		
Reply	R VALUE, value range-2147483648 ~ 2147483647, unit : N/A Alarm : -1 => R value NO. is over range.		
Example	#1=R_REG_F(1); /* If R[1]=12, #1Value=12 */		

R_REG_BIT(R_No,BIT)		Read R BIT value	R
Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● R_No=> R location NO., value range0 ~ 179999, 1000000 ~ 5999999, unit : N/A 		

Function

	<ul style="list-style-type: none"> ● BIT=>Appoint R value Bit, value range0~31, unit : N/A
Reply	<p>R Bit, value range0 ~ 1, unit : N/A</p> <p>Alarm :</p> <ul style="list-style-type: none"> -1 =>R value NO. is over range. -2 => BIT No. is over range
Example	#1= R_REG_BIT(3,2); /* If R[3]=21, #1Value=1 */

	R_REG_BIT_F(R_No,BIT)	Pre-read R BIT value	R
Description	<p>This function will pre-read R bit, easy to have pre-INT problem, so need to use WAIT(...) to use, suitable for advanced programmer to use.</p> <ul style="list-style-type: none"> ● R_No=> R location NO., value range0 ~ 179999, 1000000 ~ 5999999, unit : N/A ● BIT=>Appoint R Bit, value range0~31, unit : N/A 		
Reply	<p>R Bit, value range0 ~ 1, unit : N/A</p> <p>Alarm :</p> <ul style="list-style-type: none"> -1 =>R value NO. is over range. -2 => R value NO. is over range. 		
Example	#1= R_REG_BIT_F(3,2); /* If R[3]=21, #1Value=1 */		

	W_REG(R_No,VALUE)	Write R value	W
Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● R_No=> R location NO., value range0 ~ 179999, 1000000 ~ 5999999, unit : N/A ● VALUE =>Write info, value range-2147483648 ~ 2147483647, unit : N/A 		
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 =>R value NO. is over range. 		
Example	W_REG(2,13); /* R[2]Value=13 */		

	W_REG_SYNC(R_No,VALUE)	Write R value with SBK synchronizely	W
Description	<p>Write R value by SBK order, no need to stop INT, has limit when writing R location, this SBK will need 1 interrupt time.</p> <ul style="list-style-type: none"> ● R_No=> R location NO., value range0 ~ 179999, unit : N/A ● VALUE =>Write info, value range-1073741824 ~ 1073741823, unit : N/A 		
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 =>R value NO. is over range. -2 => R value writes over range 		
Example	W_REG_SYNC(2,13); /* R[2]Value=13 */		

	W_REG_BIT(R_No,BIT,ONOFF)	Write R BIT value	W
Description	This function will stop interpretation automatically.(Type I)		

	<ul style="list-style-type: none"> ● R_No=> R location NO., value range0 ~ 179999, unit : N/A ● BIT=>Appoint R valueBit, value range0~31, unit : N/A ● ONOFF=>write value, 0 ~ 1, unit : N/A
Reply	<p>Alarm :</p> <p>-1 =>R value NO. is over range.</p> <p>-2 => BIT No. is over value range</p> <p>-3 => ON OFF is over value range</p>
Example	W_REG_BIT(4,3,1); /* If R[4]=0 ◇ R[4]Value=8 */

	W_REG_BIT_SYNC(R_No,BIT,ONOFF)	Write R BIT by SBK SYN	W
Description	<p>Write R value by SBK order, no need to stop INT, has limit when writing R location, this SBK will need 1 interrupt time.</p> <ul style="list-style-type: none"> ● R_No=> R location NO., value range0 ~ 179999, unit : N/A ● BIT=>Appoint R valueBit, value range0~31, unit : N/A ● ONOFF=>write value, 0 ~ 1, unit : N/A 		
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 =>R value NO. is over range. -2 => BIT No. is over range -3 => ONOFF is over range 		
Example	W_REG_BIT_SYNC(4,3,1); /* If R[4]=0 ◊ R[4]Value=8 */		

	R_LV_BIT(LV_No,BIT)	Read Local Variables BIT	R
Description	<ul style="list-style-type: none"> ● LV_No =>Read local variables location No., value range0 ~199, unit : N/A ● BIT=>Appoint local variables value Bit, value range0~31, unit : N/A 		
Reply	<p>Local variables Bit, value range0 ~ 1, unit : N/A</p> <p>Alarm :</p> <ul style="list-style-type: none"> -1 => Local variables No. is over range -2 => BIT No. is over range 		
Example	#1= R_LV_BIT(3,2); /* if #3=21, #1Value=1 */		

	W_LV_BIT(LV_No,BIT,ONOFF)	Write Local Variables BIT	W
Description	<ul style="list-style-type: none"> ● LV_No =>Write local variables location No., value range 0 ~199, unit : N/A ● BIT=>Appoint local variables value Bit, value range0~31, unit : N/A ● ONOFF=>write value, 0 ~ 1, unit : N/A 		
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 => Local variables No. is over range -2 => BIT No. is over range -3 => ONOFF is over range 		
Example	W_LV_BIT(4,3,1); /* if #4=0, #4Value=8 */		

	R_GV_BIT(GV_No,BIT)	Read Global Variables BIT	R
Description	<ul style="list-style-type: none"> ● GV_No =>Read global variables location No., value range0 ~1999, unit : N/A ● BIT=>Appoint global variables value Bit, value range0~31, unit : N/A 		
Reply	<p>Global variables Bit, value range0 ~ 1, unit : N/A</p> <p>Alarm :</p> <ul style="list-style-type: none"> -1 => Global variables No. over range 		

	-2 => BIT No. is over range
Example	#1= R_GV_BIT(3,2); /* If @3=21 , #1Value=1 */

W_GV_BIT(GV_No,BIT,ONOFF)		Write Global Variables BIT	W
Description	<ul style="list-style-type: none"> ● GV_No =>Write global variables location No., value range0 ~1999, unit : N/A ● BIT=>Appoint global variables value Bit, value range0~31, unit : N/A ● ONOFF=>write value, 0 ~ 1, unit : N/A 		
Reply	<p>Alarm :</p> <p>-1 => Global variables over range</p> <p>-2 => BIT No. is over range</p> <p>-3 => ONOFF is over range</p>		
Example	W_GV_BIT(4,3,1); /* if @4=0 . @4Value=8 */		

8.6 Read/write coordinate and coordinate function

R_ABS_COOR(PATH,AXIS)		Read MOT ABS Coordinate	R
Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range1~32, unit : N/A 		
Reply	<p>MOT appoint axis ABS coordinate, unit=mm</p> <p>Alarm :</p> <p>-1 =>Read coordinate error</p>		
Example	#1= R_ABS_COOR(0,1); /* If this path ABS coordinate 1st axis=1.234mm, #1Value=1.234 */		

R_MACH_COOR(PATH,AXIS)		Read MOT MACHINE Coordinate	R
Description	<p>This function will stop interpretation automatically.(Type II)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range1~32, unit : N/A 		
Reply	<p>MOT appoint axis MACHINE coordinate, unit=mm</p> <p>Alarm :</p> <p>-1 =>Read coordinate error</p>		
Example	#1= R_MACH_COOR(0,1); /* If this path MACHINE coordinate 1 st axis=1.234mm, #1Value=1.234 */		

W_ABS_SHIFT(PATH,AXIS,CASE,VALUE)		Command MOT Coordinate Offset	W

Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range1~32, unit : N/A ● CASE =>Set up type, value range1~4, unit : N/A 1:Re-set program coordinate 2: Offset program coordinate 3:Re-set REL coordinate 4:Offset REL coordinate ● VALUE =>Write info, value rangedouble, unit=mm
Reply	: N/A
Example	W_ABS_SHIFT(0,1,1,1.234); /* This path ABS coordinate 1 st axis=1.234mm */

R_INT_PROG_COOR(PATH,AXIS)		Read INT Program Coordinate	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range1~32, unit : N/A 		
Reply	Part program read INT coordinate, unit=mm		
Example	#1= R_INT_PROG_COOR(0,1); /* read INT coordinate 1st axis value */		

INT_UPDATE(PATH,AXIS)		Make INT Coordinate & MOT Coordinate SYN	W
Description	<p>This function will stop interpretation automatically.(Type II)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range1~32, unit : N/A 		
Reply	Alarm : -1 =>Read coordinate error		
Example	INT_UPDATE(0,1); /* SYN this path 1 st axis INT coordinate and MOT coordinate */		

R_G53G59_COOR(PATH,Coor,AXIS)		Read G53~G59 Coordinate	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● Coor =>Appoint coordinate 53~59, value range 53~59, unit : N/A ● AXIS=>Appoint axis number, value range1~32, unit : N/A 		
Reply	Part program read G53~G59 coordinate, unit=mm Alarm : -1 => Appoint coordinate No. over range		
Example	#1= R_G53G59_COOR(0,55,1); /* If this path G55 coordinate 1 st axis=1.234mm, #1Value=1.234 */		

W_G53G59_COOR(PATH,Coor,AXIS,VALUE) Write G53~G59 Coordinate		W
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● Coor =>Appoint coordinate 53~59, value range53~59, unit : N/A ● AXIS=>Appoint axis number, value range1~32, unit : N/A ● VALUE =>Write info, value rangedouble, unit=mm 	
Reply	Alarm : -1 => Appoint coordinate No. is over range	
Example	W_G53G59_COOR(0,55,1,1.234); /* This path G55 coordinate 1 st axis=1.234mm */	

R_G54EXP_COOR(PATH,Coor,AXIS)		Read G54 Extension Coordinate	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● Coor =>Appoint extension coordinate 1~100, value range1~100, unit : N/A ● AXIS=>Appoint axis number, value range1~32, unit : N/A 		
Reply	Part program read G54 extension coordinate, unit=mm Alarm : -1 => Appoint coordinate No. is over range		
Example	#1= R_G54EXP_COOR(0,2,1); /* If this path P2 coordinate 1st axis=1.234mm, #1Value=1.234 */		

W_G54EXP_COOR(PATH,Coor,AXIS,VALUE)		Write G54 Extension Coordinate	W
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● Coor =>Appoint extension coordinate 1~100, value range1~100, unit : N/A ● AXIS=>Appoint axis number, value range1~32, unit : N/A ● VALUE =>Write info, value rangedouble, unit=mm 		
Reply	Alarm : -1 => Appoint coordinate No. is over range		
Example	W_G54EXP_COOR(0,2,1,1.234); /* this path P2 coordinate 1 st axis=1.234mm */		

8.7 Read/write tool info function

R_TOOL_DATA(PATH,Tool_No,TYPE)		Read INT Tool Info	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. 		

	<ul style="list-style-type: none">● Tool_No =>Appoint get tool info's too number, value range1 ~ 400, unit : N/A● TYPE =>Appoint get tool info's type, value range****, unit : N/A<ul style="list-style-type: none">1: Tool type, unit : N/A2: Tool wear diameter, unit=mm3: Tool geometry diameter,, unit=mm4: Tool index, unit : N/A5: Tool database index, unit : N/A101 ~ 132: Tool wear length 1~32 axis, unit=mm201 ~ 232: Tool geometry length 1~32 axis, unit=mm
Reply	Part program read tool info, unit=above Alarm : -1 => Appoint tool number is over range
Example	#1= R_TOOL_DATA(0,2,201); /* If Tool 2's first axis geometry length =1.234mm, #1Value=1.234 */

W_TOOL_DATA(PATH,Tool_No,TYPE,VALUE) Write INT Tool Info		W
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● Tool_No =>Appoint write tool info's tool number, value range1 ~ 400, unit : N/A ● TYPE =>Appoint write tool info's type, value range****, unit=below 2: Tool wear diameter 3: Tool geometry diameter 101 ~ 132: Tool wear length 1~32 axis 201 ~ 232: Tool geometry length 1~32 axis ● VALUE =>Write info, value range double, unit=mm 	
Reply	Alarm : -1 => Appoint tool number is over range	
Example	W_TOOL_DATA(0,2,201,1.234); /* this path Tool 2 first axis geometry tool length=1.234mm */	

8.8 I LATCH value function

W_I_LATCH(PATH,I_NO,HwifAxis_No,Ri_Fa) Setup I Latch		W
Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● I_NO => I No., value range****, unit : N/A 1~2 Card1 EPCIO LI1~2 11~12 Card2 EPCIO LI1~2 ~ 51~52 Card6 EPCIO LI1~2 101~106 Card1 CPLD LI1~6 111~116 Card2 CPLD LI1~6 ~ 151~156 Card6 CPLD LI1~6 ● HwifAxis_No=>Hardware axis No., value range****, unit : N/A 1~6:Card1 11~16:Card2 ~ 51~56:Card6 ● Ri_Fa=>1:Rising Edge,2:Falling edge, value range1~2, unit : N/A 	
Reply	: N/A	
Example	W_I_LATCH(0,101,1,1); /* Enable CPLD first I point, first axis at hardware, up trigger */	

R_I_LATCH(PATH,I_NO)		Get if I Latch happend	R
Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. 		

Function

	<ul style="list-style-type: none"> I_NO => I No., value range****, unit : N/A 1~2 Card1 EPCIO LI1~2 11~12 Card2 EPCIO LI1~2 ~ 51~52 Card6 EPCIO LI1~2 101~106 Card1 CPLD LI1~6 111~116 Card2 CPLD LI1~6 ~ 151~156 Card6 CPLD LI1~6
Reply	path Get if I Latch happen(0:N,1:Y), unit : N/A
Example	#1 = R_I_LATCH(0,101); /* Get CPLD first I signal, if triggered, #1Value=1 */

R_I_LATCH_COOR(PATH,I_NO,AXIS)		Get I Latch Coordinate	R
Description	This function will stop interpretation automatically.(Type I)		
	<ul style="list-style-type: none"> PATH => Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. I_NO => I No., value range****, unit : N/A 1~2 Card1 EPCIO LI1~2 11~12 Card2 EPCIO LI1~2 ~ 51~52 Card6 EPCIO LI1~2 101~106 Card1 CPLD LI1~6 111~116 Card2 CPLD LI1~6 ~ 151~156 Card6 CPLD LI1~6 AXIS=>Appoint axis number, value range1~6, unit : N/A 		
Reply	path Get I Latch coordinate, unit=mm		
Example	#1 = R_I_LATCH_COOR(0,101,1); /* Get CPLD first I point LATCH MACHINE coordinate value */		

8.9 Value Regularization

SPEED_STD(PATH,VALUE)		Speed Value Regularization	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● VALUE =>Write info, value rangedouble, unit(mm/min)。 		
Reply	Converts the input value to the maximum metric or inch unit mode. Metric mode (mm/min), inch mode (inch/min).		
Example	#1 = SPEED_STD(0,25.4); /* if this SBK is under inch mode, #1Value=1 inch/min */		

SPEED_STD_R(PATH,R_No)		R Speed Regularization	R
Description	<p>This function will stop interpretation automatically.(Type I)</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● R_No=> R location NO., value range0 ~ 1299999, 1000000 ~ 3999999, unit : N/A 		
Reply	Converts the input value to the maximum metric or inch unit mode. Metric mode (mm/min), inch mode (inch/min). Alarm : -1 =>R value NO. is over range.		
Example	#1 = SPEED_STD_R(0,1); /* If R[1]=25400, #1Value=1 inch/min */		

SPEED_STD_R_F(PATH,R_No)		Pre-read R Speed Regularization	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● R_No=> R location NO., value range0 ~ 1299999, 1000000 ~ 3999999, unit : N/A 		
Reply	Converts the input value to the maximum metric or inch unit mode. Metric mode (mm/min), inch mode (inch/min). Alarm : -1 =>R value NO. is over range.		
Example	#1 = SPEED_STD_R_F(0,1); /* If R[1]=25400, #1Value=1 inch/min */		

LEN_STD(PATH,AXIS,VALUE)		Length Value Regularization	R
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range0~32, unit : N/A 0 : Convert directly. 1~32 : follow path axis situation to change ● VALUE =>Write info, value rangedouble, unit(mm)。 		

Function

Reply	Converts the input value to the maximum metric or inch unit mode. Metric mode (mm/min), inch mode (inch/min).
Example	#1 = LEN_STD(0,2,25.4); /* If 2 axis is linear axis and its SBK in under inch mode, #1Value=1 inch */

LEN_STD_R(PATH,AXIS,R_No)		R Length Value Regularization	R
Description	This function will stop interpretation automatically.(Type I) <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range0~6, unit : N/A 0 : Convert directly. 1~32 : follow path axis situation to change ● R_No=> R location NO., value range0 ~ 129999, 1000000 ~ 3999999, unit : N/A 		
Reply	Converts the input value to the maximum metric or inch unit mode. Metric mode (mm/min), inch mode (inch/min). Alarm : -1 =>R value NO. is over range.		
Example	#1 = LEN_STD_R(0,2,1); /* If 2 axis is linear axis and its SBK in under inch mode , R[1]=25400, #1Value=1 inch */		

LEN_STD_R_F(PATH,AXIS,R_No)		Pre-read R value length Value	R
		Regularization	
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● AXIS=>Appoint axis number, value range0~6, unit : N/A 0 : Convert directly. 1~32 : follow path axis situation to change ● R_No=> R location NO., value range0 ~ 129999, 1000000 ~ 3999999, unit : N/A 		
Reply	Converts the input value to the maximum metric or inch unit mode. Metric mode (mm/min), inch mode (inch/min). Alarm : -1 =>R value NO. is over range.		
Example	#1 = LEN_STD_R(0,2,1); /* If 2 axis is linear axis and its SBK in under inch mode, R[1]=25400, #1Value=1 inch */		

8.10 In position function

C_INPOS(PATH,TYPE,VALUE)		Feedrate In Position Check	W
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. 		

	<ul style="list-style-type: none"> ● TYPE =>Type, value range****, unit : N/A. <ul style="list-style-type: none"> 1: Feedrate in postion check type(0:OFF,1:Axis,2:Tan), unit : N/A 2: Feedrate in postion check type reply parameter default setting (1: Notify tag), unit : N/A 3: Set up tan in postion check range, unit=mm 4: Set up tan in postion check range reply parameter default setting (1:Notify tag), unit : N/A 101~132: Set up every axis in postion check switch(0:OFF,1:ON), unit : N/A 201~232: Set up every axis in postion check switch reply parameter default setting (1:notify tag), unit : N/A 301~332: Set up every axis in position range, unit=mm 401~432: Set up every axis in position range reply parameter default setting (1:notify tag), unit : N/A 501~532: If every axis in tan in postion check switch(0:OFF,1:Combine&check), unit : N/A 601~632: If every axis in tan in postion check switch reply parameter default setting (1:notify tag), unit : N/A ● VALUE =>Write info, value range0 ~ 2147483647, unit : N/A
Reply	: N/A
Example	C_INPOS(0,301,0.123); /* Appoint first axis feedrate in postion check range 0.123mm */

	RP_INPOS(PATH,TYPE,VALUE)	Rapid In Position Check	W
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. <ul style="list-style-type: none"> 0 : Current path, 1~32 : 1 path ~6 path ● TYPE =>Type, value range****, unit : N/A. <ul style="list-style-type: none"> 1: Rapid in postion check type(0:OFF,1:every axis), unit : N/A 2: Rapid in postion check type reply parameter default setting (1:notify tag), unit : N/A 101~132: Set up every axis in postion check switch(0:OFF,1:ON), unit : N/A 201~232: Every axis in postion check switch reply parameter default setting (1:notify tag), unit : N/A 301~332: Set up every axis in position range, unit=mm 401~432: Set up every axis in position range reply parameter default setting (1:notify tag), unit : N/A ● VALUE =>Write info, value range0 ~ 2147483647, unit : N/A 		
Reply	: N/A		
Example	RP_INPOS(0,301,0.123); /* Appoint first axis rapid in postion check range 0.123mm */		


	BKCMP(PATH,TYPE,VALUE)	SBK Compare	W
Description	<ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. <ul style="list-style-type: none"> 0 : Current path, 1~6 : First path~6th path. 		

	<ul style="list-style-type: none"> ● TYPE =>Type, value range****, unit : N/A. 0: Compare1, unit=mm 1: Compare2, unit=mm ● VALUE =>Write info, value range0 ~ 2147483647, unit : N/A
Reply	: N/A
Example	BKCMP(0,1,0.123); /* Appoint SBK compare2=0.123mm */

8.11 MACRO variables stack function

PUSH(VALUE)		Push to MACRO Variable Stack	W
Description	Maximum stack amount=50		
	<ul style="list-style-type: none"> ● VALUE =>Write info, value rangedouble, unit : N/A 		
Reply	: N/A		
Example	<pre>#1=1.234 #2=5.678 STKCLR(); /* clear stacking info */ PUSH(#1); /* push #1 variables to MACRO variables to stack, amount=1 */ PUSH(#2); /* push #2 variables to MACRO variables to stack, amount=2*/ #11=STKTOP(0); /* check 1 MACRO variables stack info, #11=5.678, amount=2*/ #12=STKTOP(1); /* check 2 MACRO variables stack info, #12=1.234, amount=2*/ #13=STKTOP(2); /* check 3 MACRO variables stack info,alarm #13=VACANT, amount=2*/ #21=POP(); /* withdraw MACRO variables stack last data, #21=5.678, amount=1*/ #22=POP(); /* withdraw MACRO variables stack last data, #22=1.234, amount =0*/ #23=POP(); /* MACRO variables stack has no data, #23=VACANT, amount =0*/</pre>		

POP()		Pop info from MACRO variables stack	R
Description	N/A		
Reply	Withdraw MACRO variables stack last data, this data will be deleted from the stack, unit : N/A VACANT => MACRO variables stack has no data.		
Example	Refer to PUSH function example		

	STKTOP(STACK_NO)	Check info from MACRO variables stack	R
Description	<ul style="list-style-type: none"> ● STACK_NO =>Check info from stack's top, value range0~49, unit : N/A 		
Reply	<p>Check info from MACRO variables stack, data will not be deleted from stack, unit : N/A</p> <p>Alarm :</p> <p>-1 => Check serial number is over range</p>		
Example	Refer to PUSH function example		

	STKCLR()	Clear data in stack	W
Description	N/A		
Reply	N/A		
Example	Refer to PUSH function example		

8.12 CCD function

	W_CCD(PATH,TYPE,VALUE)	Setup CCD	W
Description	<p>This function will stop interpretation automatically.(Type I) ; function will be ignored when preview & R-restart</p> <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● TYPE =>Appoint type, refer to below description, value range****, unit : N/A ● VALUE =>Set up data, refer to below d Description, value range****, unit : N/A 0: CCD type(0:Keyence5xxx,1:Keyence7xxx), value range0~1, unit : N/A 1: Give CCD command, ex: switch to KEYENCE CCD 1 => "PW,IN,1" 2: Switch CCD program number, value range 0~999, unit : N/A 99: Set up overtime, value range1~2147483647, unit : ms 100: TCP/IP format => "IP,PORT",ex:"192.168.0.10,8500" 		

	<p>101: RS232 format => "COM_PORT,BAUD,BITS& PARITY&STOP" ,ex:"COM1,9600,812"</p> <table border="1"> <thead> <tr> <th>RS232 Format</th><th>Description</th><th>Setting</th></tr> </thead> <tbody> <tr> <td>COM_PORT</td><td>COM port</td><td>COM1,COM2</td></tr> <tr> <td>BAUD</td><td>Transmission speed(bps)</td><td>9600,19200,38400</td></tr> <tr> <td>BITS</td><td>Transmission bit(bit)</td><td>7,8</td></tr> <tr> <td>PARITY</td><td>Transmission even/odd check</td><td>0:N/A,1:Even,2:Odd</td></tr> <tr> <td>STOP</td><td>Transmission stop bit</td><td>1,2</td></tr> </tbody> </table>	RS232 Format	Description	Setting	COM_PORT	COM port	COM1,COM2	BAUD	Transmission speed(bps)	9600,19200,38400	BITS	Transmission bit(bit)	7,8	PARITY	Transmission even/odd check	0:N/A,1:Even,2:Odd	STOP	Transmission stop bit	1,2
RS232 Format	Description	Setting																	
COM_PORT	COM port	COM1,COM2																	
BAUD	Transmission speed(bps)	9600,19200,38400																	
BITS	Transmission bit(bit)	7,8																	
PARITY	Transmission even/odd check	0:N/A,1:Even,2:Odd																	
STOP	Transmission stop bit	1,2																	
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -3 => did not input string -4 => communication interface did not have initialization -6 => CCD device program is range -7 => CCD device type setting wrong -101 => TCP/IP initialization fail -102 => TCP/IP string format error -103 => TCP/IP did not connect -104 => TCP/IP send string location=empty -105 => TCP/IP send file fail -106 => TCP/IP communication brake -107 => TCP/IP receive file overtime -108 => TCP/IP set up channel fail -109 => TCP/IP switch IP fail -110 => TCP/IP connect to Server fail -201 => RS232 initialization fail -202 => RS232 COM PORT setting fail -203 => RS232 COM1 PORT not for INT, check P#40007=4 -204 => RS232 COM2 PORT not for INT, check P#40008=4 -205 => RS232 Transmission speed setting error -206 => RS232 Transmission bit setting error -207 => RS232 Transmission even/odd check setting error -208 => RS232 Transmission stop bit setting error -209 => RS232 send string location=empty -210 => RS232 send file fail -211 => RS232 receive file overtime -212 => RS232 receive file too big -213 => RS232 receive fil fail 																		
Example	<p>Example 1, use TCP/IP to connect with CCD :</p> <pre>W_CCD(0,100,"192.168.0.10,8500"); /* IP=192.168.0.10,PORT=8500 */</pre>																		

```
W_CCD(0,1,"T1"); /* wait CCD reply data */  
#1 = PASER_CCD(0,1); /* analyze CCD reply data , get 1 column value */  
#2 = PASER_CCD(0,2); /* analyze CCD reply data , get 2 column value */  
...  
#20 = PASER_CCD(0,20); /* analyzeCCDReplydata , get 20 column value */
```

Example2, use RS232 to connect with CCD :

```
W_CCD(0,101,"COM1,9600,812"); /* COM1,BAUD=9600,BITS=8,PARITY=Even,STOP=2 */  
W_CCD(0,1,"T1"); /* wait CCD reply data */  
#1 = PASER_CCD(0,1); /* analyze CCD reply data, get 1 column value */  
#2 = PASER_CCD(0,2); /* analyzeCCD reply data, get 2 column value e */  
...  
#20 = PASER_CCD(0,20); /* analyze CCD reply data, get 20 column value */
```


Example3, switch CCD program number :

```
W_CCD(0,100,"192.168.0.10,8500"); /* IP=192.168.0.10,PORT=8500 */  
W_CCD(0,2,2); /* switch CCD program number 2 */  
W_CCD(0,1,"T1"); /* wait CCD reply data */  
#1 = PASER_CCD(0,1); /* analyze CCD reply data, get 1 column value */  
#2 = PASER_CCD(0,2); /* analyze CCD reply data, get 2 column value e */  
...  
#20 = PASER_CCD(0,20); /* analyze CCD reply data, get 20 column value */
```


PASER_CCD(PATH,ITEM)		Get CCD reply data column value	R
Description	This function will be ignored when preview & R-restart <ul style="list-style-type: none"> ● PATH =>Path No., value range 0 ~6, unit : N/A. 0 : Current path, 1~6 : First path~6th path. ● ITEM =>Appoint CCD reply data column, value range1 ~20, unit : N/A 		
Reply	Get appointed CCD reply data column value, unit : N/A Alarm : -1 => over range		
Example	Refer to W_CCD function example		

8.13 MACRO dialogue function

MSG_OK("TITLE","TEXT","FILE")		Message Dialogue	W
Description	This function will stop interpretation automatically.(Type I) ; This function will be ignored when preview & R-restart <ul style="list-style-type: none"> ● TITLE =>Dialogue title, empty is allowed ● TEXT =>Dialogue message ● FILE =>Dialogue with graph name, empty is allowed If above arguments string has MACRO variables, system will replace it to be the value automatically. Refer to 5.5 string variables replace value chapter.		
Reply	Alarm : -1 => Function arguments format error -2 =>Title is over string length limit -3 => Did not input dialogue message -4 => Graph name is over string length limit		
Example	Example1 : <pre>MSG_OK("Dialogue message","welcome to use our product",""); /* Dialogue did not have graph */</pre> Example2 : <pre>MSG_OK("Dialogue message","welcome to use our product ","PIC.JPG"); /* Dialogue has graph */</pre> Example3 : <pre>#2= R_MACH_COOR(0,1); /* if this path MACHINE coordinate first axis=1.234mm, #2Value=1.234 */ MSG_OK("Dialogue message ","MACHINE coordinateX#2correct!",""); /* show "MACHINE coordinate X1.234 correct !" */</pre>		



	MSG_YES("TITLE", "TEXT", "FILE")	Inquiry Dialogue	R
Description	<p>This function will stop interpretation automatically.(Type I) ; This function will be ignored when preview & R-restart</p> <ul style="list-style-type: none"> ● TITLE =>Dialogue title, empty is allowed ● TEXT =>Dialogue message ● FILE =>Dialogue with graph name, empty is allowed <p>If above arguments string has MACRO variables, system will replace it to be the value automatically. Refer to 5.5 string variables replace value chapter.</p>		
Reply	<p>Read dialogue input button(0:N,1:Y)</p> <p>Alarm :</p> <ul style="list-style-type: none"> -1 => Function arguments format error -2 =>Title is over string length limit -3 => Did not input dialogue message -4 => Graph name is over string length limit 		
Example	<p>Example1 :</p> <pre>#1 = MSG_YES("Inquiry dialogue","if turn on LUB?",""); /* Dialogue did not have graph */</pre> <p>Example2 :</p> <pre>#1 = MSG_YES("Inquiry dialogue "," if turn on LUB?","PIC.JPG"); /* Dialogue has graph */</pre> <p>Example3 :</p> <pre>#2= R_MACH_COOR(0,1); /* if this path MACHINE coordinate first axis=1.234mm, #2Value=1.234 */ #1 = MSG_YES("Inquiry dialogue ","MACHINE coordinateX#2 correct?",("")); /* show" MACHINE coordinate X1.234 correct ?" */</pre>		



	INPUT("TITLE","TEXT","FILE",MIN,MAX,DEF)	Input Value Dialogue	R
Description	<p>This function will stop interpretation automatically.(Type I) ; This function will be ignored when preview & R-restart</p> <ul style="list-style-type: none"> ● TITLE =>Dialogue title, empty is allowed ● TEXT =>Dialogue message ● FILE =>Dialogue with graph name, empty is allowed ● MIN =>Input Min.value, value range-2147483648 ~ 2147483647, unit : N/A ● MAX => Input Max.value, value range-2147483648 ~ 2147483647, unit : N/A ● DEF => Input default value, value range-2147483648 ~ 2147483647, unit : N/A <p>If above arguments string has MACRO variables, system will replace it to be the value automatically. Refer to 5.5 string variables replace value chapter.</p>		
Reply	<p>Read dialogue input value, value range-2147483648 ~ 2147483647, unit : N/A</p> <p>Alarm :</p> <ul style="list-style-type: none"> -1 => Function arguments format error -2 => Title is over string length limit -3 => Did not input dialogue message -4 => Graph name is over string length limit -5 => Input value is over range 		
Example	<p>Example1 :</p> <pre>#1 = INPUT("Input dialogue","input moving distance(LU)?","",0,500,100); /* dialogue did not</pre>		

```
have graph */
```

Example2 :



```
#1 = INPUT("Input dialogue", "input moving distance(LU)?", "PIC.JPG",0,500,100); /* dialogue has graph */
```

Example3 :

```
#2= R_MACH_COOR(0,1); /* if this path MACHINE coordinate first axis=1.234mm,
```

```
#2Value=1.234 */
```

```
#1 = INPUT("Input dialogue", "MACHINE coordinateX#2 correct,input distance?", "",0,500,100); /* show " MACHINE coordinateX1.234 correct,input distance?" */
```



Example1

Example2

Example3

Result : After inputing, press"OK", #1=100 °


MENU("TITLE","TEXT","FILE",DEF)

Menu Dialogue

R

Description	<p>This function will stop interpretation automatically.(Type I) ; This function will be ignored when preview & R-restart</p> <ul style="list-style-type: none"> ● TITLE =>Dialogue title, empty is allowed ● TEXT =>Dialogue message ● FILE =>Dialogue with graph name, empty is allowed ● DEF =>Input menu default value, value range1 ~ 10, unit : N/A <p>If above arguments string has MACRO variables, system will replace it to be the value automatically. Refer to 5.5 string variables replace value chapter.</p>
	<p>Menu dialogue reply value item 1~10, value range1~10, unit : N/A</p> <p>Alarm :</p>
Reply	

	<ul style="list-style-type: none"> -1 => Function arguments format error -2 => Title is over string length limit -3 => Did not input dialogue message -4 => Graph name is over string length limit -5 => Did not have any list -6 => Menu default value is over item numbers
	<p>Example1 :</p> <pre>MENU_ADD("Turn oncoolant",""); MENU_ADD("Turn offcoolant",""); MENU_ADD("Turn onworking lamp",""); MENU_ADD("Turn offworking lamp",""); #1 = MENU("Menu dialogue ","choose work item?","",1); /*Dialogue did not have graph */</pre> <p>Example2 :</p> <pre>MENU_ADD("Turn oncoolant","WATER.JPG"); MENU_ADD("Turn offcoolant","WATER.JPG"); MENU_ADD("Turn onworking lamp","LIGHT.JPG"); MENU_ADD("Turn offworking lamp","LIGHT.JPG"); #1 = MENU("Menu dialogue "," choose work item?","PIC.JPG",1); /* Dialogue has graph */</pre> <p>Example3 :</p> <p>Example</p> <pre>MENU_ADD("Turn oncoolant",""); MENU_ADD("Turn offcoolant",""); #2= R_MACH_COOR(0,1); /* if this path MACHINE coordinate first axis=1.234mm, #2Value=1.234 */ #1 = MENU("Menu dialogue ","MACHINE coordinateX#2, choose work item?","",1); /*Dialogue did not have graph */</pre>

	 <p>Example1</p>	<p>Example2</p>
	<p>Example3</p> <p>Result : when choosing item=Turn off coolant, #1=2</p>	

	MENU_ADD("TEXT","FILE")	Menu Dialogue Setting	W
Description	<p>This function will be ignored when preview & R-restart</p> <p>This function is to add menu dialogue content, every call will add one menu item, maximum can be 10 items. When calling MENU(...)function, this new adding menu by this path will be cleared after popping up dialogue.</p> <ul style="list-style-type: none"> ● TEXT =>Menu item ● FILE =>graph name, empty is allowed 		
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 => Function arguments format error -2 => Title is over string length limit -3 => Did not input dialogue message -4 => Graph name is over string length limit -5 => Menu item is over range 		
Example	Refer to MENU function example		

	PLOT_ADD("FILE","LEGEND")	Curve Data File Name Setting	W
Description	<p>This function will be ignored when preview & R-restart</p> <p>This function is to add curve data file name, every call will add one curve data, maximum one can be up to 10 datas. After calling PLOT_SHOW(...)function, pop up will clear all curve data names.</p> <ul style="list-style-type: none"> ● FILE =>Curve data file name ● LEGEND =>Curve data description 		
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 => function arguments format error -2 => Did not input menu content -3 => Curve data file name over string length limit 		

	-4 => Curve data string over string length limit -5=> Curve data amount over range
Example	Refer to PLOT_SHOW function example

PLOT_SHOW("TITLE","TEXT","XLB","YLB") 曲線圖框 W	
Description	<p>This function will stop interpretation automatically.(Type I) ; this function will be ignored at graph preview and R-restart.</p> <ul style="list-style-type: none"> ● TITLE => frame title, empty is allowed ● TEXT => frame message, empty is allowed ● XLB => frame X axis tag, empty is allowed ● YLB => frame Y axis tag, empty is allowed <p>If above arguments string has MACRO variables, system will replace it to be the value automatically. Refer to 5.5 string variables replace value chapter.</p>
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 => function arguments input format error -2 => frame message is over string length limit -3 => frame X axis tag is over string length limit -4 => frame Y axis tag is over string length limit -5 => did not input curve data
Example	<pre>PLOT_ADD("DATA1.TXT","data1"); /* 1 data */ PLOT_ADD("DATA2.TXT","data2"); /* 2 data */ PLOT_SHOW("Curve frame","voltage data","time(ms)", "Votage(mV)");</pre>

8.14 MACRO write function

OPEN("FILE") Open file W	
Description	<ul style="list-style-type: none"> ● FILE => write file name. <p>Open file, when open file command is valid, PRINT command can be used. Multi-part program can not be opened at the same time, only one file at one time.</p> <p>If above arguments string has MACRO variables, system will replace it to be the value automatically. Refer to 5.5 string variables replace value chapter.</p>
Reply	<p>Alarm :</p> <ul style="list-style-type: none"> -1 => function arguments input format error. -2 => Do not input file name. -3 => File name is over string length limitation. -4 => Do not close previous file. -5 => open file fail.
Example	Usage Example 1 :

```

@15=10
@20=2
#3=1
#20=9
OPEN("A12345");
PRINT("G0 Y@15 X4");           /* export to file result : G0 Y10 X4 */
PRINT("G0 Y@15 X#3");          /* export to file result : G0 Y10 X1 */
PRINT("X100 Z10 F200");        /* export to file result : X100 Z10 F200 */
PRINT("G0 Y(@15+15.5) X4");    /* export to file result : G0 Y(10+15.5) X4 */
PRINT("G0 Y#1 X4");            /* export to file result : G0 Y   X4 */
CLOSE();
M30

Usage Example 2 :
@15=10
@20=2
#3=1
#20=9
OPEN("A12345");
PRINT("G0 X4 Y(#15+#20)");      /* export to file result : G0 X4 Y(#15+9) */
PRINT("G0 X\@20 Y\#15");        /* export to file result : G0 X@20 Y#15 */
PRINT("G0 X(@20+\#3) Y(#30+@20)"); /* export to file result : G0 X(2+\#3) Y(#30+2) */
PRINT("G0 X(@15/\#3) Y(15+@\#20)"); /* export to file result : G0 X(@15/\#3) Y(15+@20) */
PRINT("G0 X(\#3+5) Y(#30+\#3)");  /* export to file result : G0 X(#3+5) Y(#30+1) */
PRINT("G0 X(\@15*5.45) Z(#15-\#3)"); /* export to file result : G0 X(@15*5.45) Z(#15-\#3) */
PRINT("G0 Y(#15+@\#20) Z(#15\@20)"); /* export to file result : G0 Y(#15+2) Z(#15/@20) */
CLOSE();
M30

```

	CLOSE()	Close file	W
Description	Close the file that was opened by OPEN command. File will be closed automatically when part program closes or system resets. After file closed, PRINT command is invalid.		
Reply	N/A		
Example	Refer to open function example		

	PRINT("STRING")	Write file string	W
Description	This function will stop interpretation automatically(Type I) : function will be ignored when simulation and program restart. STRING =>Any string, if above arguments string has MACRO variables, system will replace it to		



	be the value automatically. Refer to 5.5 string variables replace value chapter.
Reply	Alarm : -1 => function arguments input format error. -2 => do not open file.
Example	Refer to open function example

9 Variables

This chapter is to explain whole series of INT mode.

Version : Milling machine INT mode **mill_int_Ver03.01.01**

9.1 Variables range menu

No.	Name	MACRO	HMI	Memory
#00	NULL	Read only	Read only	N
#01~#199	Local variables	Read/write	Read only	N
@0000	NULL	Read only	Read only	N
@0001~999	End-user global variables	Read/write	Read/write	Y
@1000~1999	System global variables	Only system MACRO Read/write	By user authority Read/write	N
@5000~5999	Shared path end-user global variables	Read/write	Read/write	Y
@6000~6999	Shared path system global variables	Only system MACRO Read/write	By user authority Read/write	N

9.2 Number range classification

(1). Local Variables :

#00 : always empty.

#01 ~ #199 : read/write

For every level's program, there are 199 local variables. If you cancel this level's program, variables will be canceled. But if you press RESET, it will go back to main program level, and main level's local variables was determined by P#50004.1. If you press RESET, you can not cancel this. But if you reboot the controller, every level's local variables will be canceled.

(2). Global Variables :

All levels of the program shared this common variable at single path.

@0000 : Always empty.

@0001 ~ @0999 : User global variables range, only suitable for its path, value clear will be determined by P# 50005.1 whether booting or pressing RESET.

@1000 ~ @1999 : System global variables range, only suitable for its path system MACRO, value clear will be determined by pressing RESET.

@5000 ~ @5999 : User global variables range, suitable for all paths, value clear will be determined by P#

50006 whether booting or pressing RESET.

@6000 ~ @6999 : System global variables range, suitable for all path system MACRO, value clear will be determined by pressing RESET.

9.3 Local variables and global variables BIT Function Usage Description

You may need to have a lot of tags to help MACRO procedure judge, this tag will use a lot of local variables, therefore we provide local/global variable BIT to help you solve this problem, example as below :

- BIT usage format =#i.j, also in the i=variables number range : j=2 digits , Value range=00~31
- #1.00 =>Means#1 Bit0
- #1.03 => Means #1 Bit3
- #1.3or #1.30=> Means #1 Bit30
- #1.32=>Bit uses over 32 apponts, system will show alarm : MACRO variables numbers is over range.
- #(1+0.31)=># Parentheses do not support Bit, left side means #1
- #1=123 => Left side means #1 appointed value 123
- #1.00=123 =>Bit operation, right side is bigger than 0=True. Left side means #1 appointed value 1
- #1.02=456=> Bit operation, right side is bigger than 0=True. Left side means #1 appointed value 4
- #3 = #1.02 =>#3 appointed =#1 Bit2. Left side means #3 appointed value 1
- #3.04 = #1.02 =>#3 Bit4 appointed =#1 Bit 2. Left side means#3 appointed value 16
- #1= R_REG(5) =>If R[5]=123. Left side means#1appointed value 123
- #1.00= R_REG(5) => If R[5]=123. Left side means #1 appointed value 1
- #1.02= R_REG(5) => If R[5]=123. Left side means #1 appointed value 4
- #3 = R_REG_BIT(5,2) => If R[5]=5, #3 appointed=R[5] Bit2. Left side means #3 appointed value1
- #3.04 = R_REG_BIT(5,2) => If R[5]=5, #3 Bit4 appointed =R[5] Bit2. Left side means #3 appointed value 16

9.4 Note

Between "/*" and "*/" , those input will be canceled.

Example :

```
/* test1 */;  
G00 X10. /* test 2 */;  
/* test3 */ G01 Y20.;  
G01 X10. Y20.; /* test
```

9.5 Variables to value function in string

Version : Mill_int_Ver03.01.34

When editing program or MACRO, you may need sting, ex : G65 "string" or : ALARM("string"). If you want to mix MACRO variables in this string(value of global variable'@', local variable'#'), you can use this function to show some MACRO calculating value or system info in it. It's easy for user to understand program or MACRO current situation from string, example as below :

```
#1=R_MACH_COOR(0,1); /* If this path MACHINE coordinate 1 axis= 1.234mm, #1 value=1.234 */
ALARM("MACHINE coordinate X#1mm"); /* Alarm 610000, string : " MACHINE coordinate X1.234mm" */
```

From above example, you can see the sting is within " ", and #1 is MACRO variables. When running to ALARM MACRO command, system will send alarm, and show string " MACHINE coordinate X1.234 correct", #1 will change to be value automatically.

Valid digits :

MACRO variables with () and numbers can appoint valid digits for MACRO variables to change to be value, rules are :

- When this is integer value, it will add a zero in front of this value.

EX : When #1=12, string will be

" MACHINE coordinate X#1(4)mm" => " MACHINE coordinate X0012 mm"

EX : When #1=1234567, if the value is over valid digits, it will not do any changes.

" MACHINE coordinate X#1(4)mm" => " MACHINE coordinate X1234567mm"

- When this is not integer value, it will add zero after this value to be a valid value.

EX : When #1=12.34, string will be

" MACHINE coordinate X#1(4) mm" => " MACHINE coordinate X12.3400 mm"

EX : When #1=12.345678, string will be

" MACHINE coordinate X#1(4) mm" => " MACHINE coordinate X12.3456 mm"

Stop changing digit :

You can add '\ with MACRO variables to make it stop changing value.

EX : When #1=12.345678, string will be

"MACRO calculating result \#1 = #1" => " MACRO calculating result #1 = 12.345678"

10 System M Code

This chapter is to explain whole series of INT mode.

Version : Mill_int_Ver03.01.56

10.1 INT use M code

Program Command	Description	System M Code
SYS_SUB_CALL P_	Call system sub routine	99900001
SYS_SUB_CALL "string"	P : calling file name number(O+ P_No)	
SYS_SUB_CALL "string" P_	"String" : any sting "String" P_ : calling file name(string+4digitsP_NO)	
AXIS_FREE	Free path axis	99900003
PATTERN_BEGIN	Pattern begin	99900004
PATTERN_END K_D_E_ P_	Pattern end K : If there is argument, it means relative MACRO layers. If not, it's current layer. D : Appoint pattern start letters E : Appoint starting letters' number P : Appoint insert file's number(sys_single_pattern+P_No)	99900005
DIS_HMIPLOT_ON	HMI ON	99900006
DIS_HMIPLOT_OFF	HMI OFF	99900007
MUTE_ON	Mute ON	99900008
MUTE_OFF	Mute OFF	99900009
RESTART_OK	Restart OK	99900010
RES_RESIDUAL	Run return to rest SBK manually	99900012
HIDE_SHIFT_ON	Shift OFF, make G51,G51.1,G68,G41,G42 invalid. Usually use on changing tool MACRO command which did not need to shift.	99900013
HIDE_SHIFT_OFF	Shift ON	99900014
SBK_OFF	SBK OFF	99900015
SBK_ON	SBK ON	99900016
FIX_RAPID_OR_OFF	Fixed RAPID OVERRIDE 100% OFF	99900017
FIX_RAPID_OR_ON	Fixed RAPID OVERRIDE 100% ON	99900018
FIX_CUT_OR_OFF	Fixed CUT OVERRIDE 100% OFF	99900019
FIX_CUT_OR_ON	Fixed CUT OVERRIDE 100% ON	99900020
PRIORITY_OFF	PRIORITY OFF. Lower priority when meeting stop INT in a path or SBK full	99900021

PRIORITY_ON	PRIORITY ON	99900022
-------------	-------------	----------

10.2 Kernel system M code

Part program command	Description	System M Code
PRO_STOP	Notify OP stop(the same to M0)	-3
OPT_STOP	Notify OP selective stop(the same to M1)	-4
MDI_FIN	Notify OP, MDI end	-5
INS_MACRO_FIN	Notify OP, PLC insert part program end	-12
PROG_END	Program end, system reset	-13
INTO_MREADY	Program end, NC ready	-14
MDI_TO_RY	MDI ready	-24
MDI_TO_BS	MDI stop	-25
FIX_AUTOMODE_ON	Fixed mode selection is auto mode	-26
FIX_AUTOMODE_OFF	Return mode control by R bit	-27

11 Appendix

11.1 Milling machine system MACRO list

System MACRO File Name	Function Description
sys_func_mdi1	MDI MACRO
sys_func_mr1	Retun MACRO manually with movement
sys_func_mr_residual	Retun MACRO manually without movement
sys_func_prog_restart1	Program Restart Call System MACRO
sys_func_cycle_cancel	G80 Call System MACRO automatically after canceling cycle
sys_modal_g73	G73 Rapid Peck Drilling Cycle
sys_modal_g74	G74 Left-Handed Screw Thread Tapping Cycle
sys_modal_g76	G76 Fine Boring Cycle
sys_modal_g81	G81 Drilling Cycle/Spot Boring
sys_modal_g82	G82 Drilling Cycle/Counter Boring
sys_modal_g83	G83 Peck Drilling Cycle
sys_modal_g84	G84 Right-Handed Screw Thread Tapping Cycle
sys_modal_g85	G85 Reaming Cycle
sys_modal_g86	G86 Boring Cycle
sys_modal_g87	G87 Back Boring Cycle
sys_modal_g88	G88 Boring Cycle
sys_modal_g89	G89 Reaming Cycle
sys_macro_g10	G10 Data Input Setting
sys_macro_g27	G27 Return to Origin Check
sys_macro_g28	G28 Return to the First Reference Point
sys_macro_g29	G29 Return from the First Reference Point 00
sys_macro_g30	G30 Auto Return to the 2nd, 3rd and 4th Reference Points
sys_macro_g31	G31 Skip Signal Abort Block
sys_macro_g53	G53 Rapid Positioning of Machine Coordinate System
sys_macro_g92	G92 Coordinate Setting 00
sys_macro_m0	Program stop
sys_macro_m1	Optional stop
sys_macro_m2	End of program
sys_macro_m30	Program rewind
sys_macro_m2000	Waiting M code
sys_macro_m2010	Wait for free axis command